



# Repair Price Guide

Badge & Battery	
Badge	R 290
Battery replacement	R 1 200
Bonnet	
Minor scratches (less than 5cm)	R 1 500
Minor scratch (less than 10cm)	R 1 800
Scratched & Damaged	R 2 500
Replacement	R 3 597
Boot	
Minor scratch (less than 5cm)	R 1 750
Scratch & dent (less than 10cm)	R 2 000
Damage	R 3 546
Replacement	R 3 700
Bumpers	
Plastic bumper scratched	R 450
Minor scratches (corner only) Less than 5cm/No cracks	R 1 500
Replacement for black bumper	R 1 900
Scratched from (per bumper)	R 1 900
Replacement & spray paint of plastic bumper (per bumper)	R 2 500
CD Player	
Trim	R 1 500
Installation	R 1 600
Doors	
Broken door handles	R 499
Minor scratches (corner/side only) Less than 5cm	R 1 500
Scratch & minor dent less than 10cm	R 2 000
Damage	R 2 500
Replacement	R 3 200
Dust Road Driving	
Dust Road Driving	R 799
Dents	
Small with no paint damage	R290
Medium with no paint damage	R 390
Large with no paint damage	R 590
Fender	
Minor scratch (less than 5cm)	R 1 200
Damaged from	R 1 850
Replacement	R 2 200
Grill, Hubs, Jack	
Grill	R 750
Hub cap damage: replacement	R 250
Jack from	R 350
Lights	
Flicker units x1	R 250
Lights x1 from	R 390
Rear repair/replacement (Mazda)	R 1 200
Rear repair/replacement (Golf)	R 950

Keys	
Lost/damaged keyring	R 50
Lost gear lock key	R 800
Lost ignition key from	R 1 500
Lost key: factory fitted (gearlock)	R 1 800
Mags	
Scratched mags from (each)	R 750
Mirrors	
Scratches	R 450
Replacement	R 950
Number Plate	
Number plate replacement	R 300
Rims	
Painted rim scratch only	R 250
Painted rim scratch & damaged: alignment	R 449
Replacement (each)	R 1 299
Puncture	
Puncture	R 60
Roof	
Scratches (less than 5cm)	R 1 500
Scratches (less than 15cm)	R 2 000
Damage	R 3 500
Seat	
Seat damage (per tear & hole)	R 650
Sill	
Scratch (less than 5cm)	R 1 500
Damage from	R 2 500
Sticker Removal	
Small sticker removal	R 50
Big sticker removal	R 300
Tyres	
Tyres from (each)	R 950
Vacuum & Valet	
Vacuum & wash	R 50
Light Valet	R 150
Full valet	R 300
Windows/Windcreens	
Small window replacement	R 550
Large side window replacement	R 1 200
Windscreen chip/small crack	R 350
Windscreen damaged Golf & Mazda	R 1 698
Windscreen damaged Atos	R 2 448
Alignment & Balancing	
Wheel balancing	R 390
Wheel alignment	R 390

Call Us: 081 8000 300/400

Mail Us: [info@motorent.co.za](mailto:info@motorent.co.za)